

Product Discontinuation Notices

December 1, 2008

Photoelectric Sensors

No. 2008269E

Discontinuation Notice of Mapping sensor. F3M series

Product Discontinuation

Mapping Sensor



F3M-S625 F3M-S825
F3M-S626 F3M-S826
F3M-S1213



Recommended Replacement

No recommended replacement
Please contact the appropriate
division

Discontinuation date : The end of October, 2008

Caution on recommended replacement

Not available

Product Discontinuation and recommended replacement

Product discontinuation		Recommended replacement	
Model	Product code	Model	Product code
F3M-S625	F3M 1003C	No recommended replacement Please contact the appropriate division	
F3M-S626	F3M 1004A		
F3M-S825	F3M 1001G		
F3M-S826	F3M 1008D		
F3M-S1213	F3M 1005M		